

Work Order ID 150818

Tuesday, September 20, 2016 10:19:30 AM

150818

Page 1

Item ID: D412-783-011 Repair

Accept

N900040100

Setup Start

NS1

Revision ID:

Stop

NS2

Item Name: Gross Weight Towing Cable

Start Date: 9/14/2016 Start Qty: 1.00

1

Cust Item ID:

Required Date: 9/15/2016 Req'd Qty: 1.00

1

Customer: CNATI09

Reference: RMA RA112382

Approvals: Process Plan: SWDate: SEP 20 2016

Tooling:

Date:

Run Start

NR1

QC:

Date:

SPC (Y/N):

Date:

Stop

NR2Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

Draw Nbr

Revision Nbr

D3943

E

IIN-D412-783

C

0.00

100

QC

Memo

0.00

Quality Control

CUSTOMER RETURNED D412-783-011 X1 B135000 FOR CALIBRATION PD 160920

NORMAL WEAR HAS BEEN FOUND ON INSPECTION.

PERFORM CALIBRATION AS PER IIN 412-78 16-9-28

110

QC4- 100% Inspect kits for completeness

0.00

110

QC

Memo

0.00

Quality Control

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____	
Description Work Order Deviation				Disposition					

Root Cause				FAULT CATEGORY			
Environment ☐	Design ☐	Doc/Data ☐	Equip/Tooling ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐
Handling/Pre ☐	Material ☐	Internal Transport ☐	Tribal Knowledge ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐
LOA ☐	Substation ☐	Past Expiry Date ☐	Misidentified ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐
				Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐
				Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐
				Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐
				Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐
				Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐
				Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐
				Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐
				OTHER : _____			

Work Order ID 150818***150818***

Page 2

Tuesday, September 20, 2016 10:19:30 AM

Item ID: D412-783-011 Repair Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Gross Weight Towing Cable
Start Date: 9/14/2016 Start Qty: 1.00 ***1*** Cust Item ID:
Required Date: 9/15/2016 Req'd Qty: 1.00 ***1*** Customer: CNATIO9
Reference: RMA RA112382

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
120	Identify as per dwg & Stock Location: _____	0.00							
120									
Packaging	Memo	0.00							
Packaging	ID AS REPAIR WITH NEW BATCH AT CHG 004 AND RETURN TO CUSTOMER								
130	QC21- Final Inspection - Work Order Release	0.00							
130									
QC	Memo	0.00							
Quality Control									

DAS 27 9-89
SEP 30 2016

DAS 21 9-89
OCT 03 2016
gem 11/09/30

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
				Completed By					
				Lead hand / Supervisor Approval Verification					
				QC / QA Coordinator Approval					

Root Cause				FAULT CATEGORY							
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong	☐
Design	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions	☐
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance	☐
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect	☐
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing	☐
Material	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved	☐
Internal Transport	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing	☐
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish	☐
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread	☐
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence	☐
Past Expiry Date	☐	Manufacturing Process	☐	OTHER : _____							
Misidentified	☐	Past Due	☐								

Picklist Print

Tuesday, September 20, 2016 10:19:46 AM

Page 1

Work Order ID: 150818

150818

Parent Item: D412-783-011 Repair

D412-783-011 Renair

Parent Item Name: Gross Weight Towing Cable

Start Date: 9/14/2016

Required Date: 9/15/2016

Start Qty: 1.00

Required Qty: 1.00

Comments:

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D412-783-011 Repair		Manufactured	No				Each	0.0000		1			
D412-783-011 Renair									**	<u>B135000</u>			DAS 9 9-89
Gross Weight Towing Cable													

DAS
27
9-89

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					

Root Cause				FAULT CATEGORY			
Environment ☐		No Re-verification ☐		Pressure/Forced ☐		Temperature/Cure ☐	
Design ☐		Operator ☐		Bending ☐		Set-up ☐	
Doc/Data ☐		Offset/Setup ☐		Centre Not Concentric ☐		BOM/Route ☐	
Equip/Tooling ☐		Supplier ☐		Cracks ☐		Broken/Damage/Defect ☐	
Handling/Pre ☐		Training ☐		Crimp/Kink/Ripple/Wave ☐		Inspection Incomplete/Unqualified ☐	
Material ☐		Use for Testing ☐		Cuffs ☐		Contamination ☐	
Internal Transport ☐		Poor Information ☐		Crushing ☐		Countersink ☐	
Tribal Knowledge ☐		Rushing ☐		Heat Treat ☐		Cut Too Short ☐	
LOA ☐		Product Improvement ☐		Wave/Twist in Tube ☐		Instructions Incomplete/Unclear ☐	
Substation ☐		Process Improvement ☐		Marks/Chatter ☐		Drill Holes ☐	
Past Expiry Date ☐		Manufacturing Process ☐		OTHER : _____			
Misidentified ☐		Past Due ☐					

4.0 CALIBRATION

4.1 Calibration of the D3943-041 Tow Crank Assembly

4.1.1 The chain ratchet handle on the D3943-041 Tow Crank Assembly must be calibrated annually to ensure the handle indicates "clicks" when a 3500 lbs – 4000 lbs load has been achieved. To calibrate loosen setscrew that locks the threaded stainless steel ball plunger (Refer to figure 2 for details). Place a load cell inline and ratchet until the 3500 lbs – 4000 lbs has been reached. If the handle clicks before the 3500lbs load then turn plunger clockwise 1/8 turn, remove load and retry. If handle does not click between the 3500lbs and 4000 lbs load, turn plunger 1/8 turn counterclockwise, remove load and retry. Once the handle has been properly set retighten setscrew and test once more.

4.1.2 The Tow Crank Assembly may be returned to DART for calibration, at the operator's expense.

5.0 PARTS LIST

QTY -011	PART NUMBER	DESCRIPTION
X	D412-783-011	GROSS WEIGHT TOWING KIT
1	D3943-041	TOW CRANK ASSEMBLY
1	D3949-043	FLAG ASSEMBLY
1	D3951-041	EQUIPMENT BAG
2	D3954-1	GWT PIN
2	D3954-3	GWT KNOB

INTERNAL CALIBRATION CERTIFICATE

Instrument #	Description	Serial #
D412-783-011	Ground Handling Crank Assembly	B150818

Calibrated by	Date of calibration	Calibrated with	Due	Certificate #
PD	20/09/16	Eng-07		

New tool	Disposed	In Repair	On Hold	Being Calibrated

Employee	Department	Comments:
N/A	N/A	MUST BE CALIBRATED WITH IN 1 YEAR OF PURCHASE OR FIRST OPERATION

Spec.	Tolerance is + /-	Result	Pass Fail
3500LBS	3500-3700LBS		Pass

Entered By:

Pat Duval